

# MONUMENT RECORD

Corner I.D. #

PERRY


G - 17

STATE OF INDIANA - COUNTY OF MONROE


Section 20, Township 8 NORTH, Range 1 WESTMonument Description & Remarks: RAILROAD SPIKE FOUND 2" BELOW GRADE

MARKING THE SOUTH 1/4 OF SECTION 20

Recovery Tie Drawing



- A. R.R. SPIKE 2" BELOW GRADE
- B. R.R. SPIKE 2" BELOW GRADE  
S 85° E, DIST 22.5'
- C. MAG W/SHINER IN 10" PWR POLE  
S 73° W, DIST 62.2'
- D. 2" ALUM DISK ON 24" CONC. PWR  
POLE S 75° E, DIST 99.0'
- E. TELEPHONE PEDESTAL  
S 07° W, DIST 13.7'
- F. TELEPHONE PEDESTAL  
N 00° W, DIST 17.2'



● At Corner



Not To Scale

State of Indiana

County of MONROE

I, STEVEN V. FARKAS, hereby certify  
that this document was prepared under my direction in  
accordance with the provisions of Section 17-3-64-4  
through 17-3-64-8 of the Indiana Code, being Acts of 1965,  
Chapter 319; and the above data is given under my hand and  
seal this \_\_\_\_\_ day of \_\_\_\_\_, 20\_\_\_\_ A.D.

Space  
Reserved For  
Recording  
Officer

Indiana Registered Land Surveyor No. \_\_\_\_\_ or

United States Government Agency \_\_\_\_\_

Title \_\_\_\_\_

Field Book:

Page:

**MONUMENT RECORD**  
**State of Indiana - County of Monroe**

**Section: 20**

**Township: 8 North**

**Range: 1 West**


**Corner ID: Per G-17**

**Monument Description & Remarks:** Found Railroad Spike (point A) in centerline of Church Lane at South 1/4 corner of section, 22.51' west of second railroad spike in centerline (point E) erroneously referenced as corner by William Bateman, R.L.S. in 1983. Monument is in line with property boundary on north/south line.  
**References on file in the County Surveyor's Office:** "May Boundary" survey prepared by Smith Quillman, dated May, 1991. Mundy survey dated September, 1997, Book 4, Page 345, Recorder's

**RECOVERY TIE DRAWING**

Field Book 98-01 Page No. 19 (Reference Field Book 97-02, Page No. 68)

USGS Clear Creek Quad



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code, and the above data is given under my hand and seal this 8th day of January, 1998.

*Kevin P. Enright*

Administered by: *Surveyor Review Board*



## MONUMENT RECORD

STATE OF INDIANA - COUNTY OF MONROE

SECTION 29, TOWNSHIP 8 NORTH, RANGE 1 WEST


## MONUMENT DESCRIPTION &amp; REMARKS

RAILROAD SPIKE SET IN CENTERLINE OF CHURCH LANE BY WILLIAM

BATEMAN R.L.S. # 12056 CORNER TIE INFORMATION ALSO FROM

MR. BATEMAN TIES CHECKED BY MICHAEL FRILEY

## RECOVERY TIE DRAWING

STATE OF INDIANA  
COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 25 TH DAY OF AUGUST, 1983 A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:  
PERRY

CORNER I.D.

G - 17

TITLE \_\_\_\_\_

This Corner Reference is incorrect. See tie sheet dated 1-8-98

JOB # 83-46

74

AUG. 10, 1983

III F 88

∞ K P

CLEAR 90°

P.K. IN 24"  
MAPLE

Set P.R. SPR @  
N.E. Cor of N.W 1/4  
SEC 29 T-8-N R-1-W  
MONROE CO.

P.K. IN 30"  
WILLOW CHERRY

APPROX  
CHURCH LANE

STONE WALL

P.K. IN WOOD  
Fence POST

P.K. IN  
WOOD FENCE POST

CERTIFIED CORRECT  
William D Bateman  
WILLIAM D BATEMAN  
RLS #12056